

## SpiceJet Dubai-Kochi flight suffers tyre burst

- A Monitor Desk Report

Date: 05 July, 2023



A SpiceJet aircraft coming from Dubai to Kochi on Tuesday (July 4) morning suffered a tyre burst but the plane made a smooth landing, according to the airline.

The airline said the tyre burst was noticed post landing of the aircraft. Details about the number of passengers onboard the plane could not be immediately ascertained.

"On July 4, SpiceJet Boeing 737 operated flight SG-17, Dubai (DXB) - Cochin (COK). During post flight walk around, NO 2 tyre was found burst," the airline said in a statement. All system parameters were normal during and post flight and landing was smooth, it added.

-B